

# CERATIN®









Turnerbars non treated after 100.000 copies full of pollution. This will definitive cause problems like foulds in the paper and will result in printingdefects



Turnerbars treated with Antracit Grey CERATIN® after 200.000 copies with no pollution visible. The rollers stayed clean for several days more after this.

## Usage and advantages

- Special treatment of the surface
- Multiple layers of the CERATIN® Coating
- The surface will be very resistant against high Mechanical and chemical demands
- Polution (built up) with printing inks will be postponed and decreased
- Easier and faster cleaning



CERATIN® close up pictures of the surface treatment

print efficiency  
**4c**

### NIEDERLANDE

Postbus 33  
7000 AA Doetinchem  
Niederlande

Telefon : +49 2822 9779364  
Telefax : +49 2822 9779365

Web : [www.4cinks.com](http://www.4cinks.com)